ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0531, W0292	NA, 3rd Crs Lakshmi Sagar Lyt	Veeranna layout & thindul surroundings
Segment No.	**Total Length (m)**	
9/S-W0531/S100930	144.89	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	87.61	77.565031	13.070093	77.565810	13.069882	M0006	W0465
2	57.28	77.568245	13.073216	77.568219	13.072699	W0328	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements and Asphalting to Veeranna layout Goutam book store road and thindul surroundings in ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-	100000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Improvements and Asphalting to Veeranna layout Goutam book store road and thindul surroundings in ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone Modified work	009-16-000031
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/67/2016-17	11/07/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
11/07/2016	10/07/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL BANGALORE		0.00
Phone No.	**E-Mail ID**	

9449863065

Field Inspection Details

Number of Trees	Any Other Information	Name
12		MADHAVA RAO
Date of Inspection	**Remarks**	
10/12/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	10/12/2016	09/01/2017	COMPLETED
SE	VASU K M	10/12/2016	09/01/2017	COMPLETED
EE	YARAPPA REDDY	10/12/2016	09/01/2017	COMPLETED
AEE	SHIVAKUMAR	10/12/2016	09/01/2017	COMPLETED
AE	MADHAV RAO	10/12/2016	09/01/2017	COMPLETED
AE	MADHAV RAO	10/12/2016	09/01/2017	COMPLETED